

CORRES. CONTROL
INCOMING LTR NO.

00948 RF03

DUE DATE
ACTION

RECEIVED

2003 OCT 15 A 9:34

STATE OF COLORADO

Bill Owens, Governor

Douglas H. Benevento, Executive Director

CORRESPONDENCE

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S.
Denver, Colorado 80246-1530
Phone (303) 692-2000
TDD Line (303) 691-7700
Located in Glendale, ColoradoLaboratory and Radiation Services Division
8100 Lowry Blvd.
Denver, Colorado 80230-6928
(303) 692-3090<http://www.cdphe.state.co.us>Colorado Department
of Public Health
and Environment

DIST.	LTR	ENC
BERARDINI, J. H.	X	
BOGNAR, E. S.	X	
BROOKS, L.	X	
BUTLER, L.	X	
CROCKETT, G. A.	X	
DECK, C. A.	X	
DEGENHART, K. R.	X	
DIETER, T. J.		
DIETERLE, S. E.		
FERRERA, D. W.	X	
GIACOMINI, J. J.		
HIETT, S. B.	X	
ISOM, J. H.		
LINDSAY, D. C.	X	
LONG, J. W.		
LYLE, J. L.		
MARTINEZ, L. A.	X	
NAGEL, R. E.	X	
NORTH, K.	X	
PARKER, A. M.	X	
RODGERS, A. D.	X	
SHELTON, D. C.	X	
SPEARS, M. S.		
TRICE, K. D.		
TUOR, N. R.	X	
WILLIAMS, J. L.		
ZAHM, C.	X	
Wiemelt, K.	X	
Freiboth, C.	X	
NYST, S.	X	

October 10, 2003

Mr. Joe Legare

Acting Assistant Manager for Environment and Stewardship

U.S. Department of Energy, Rocky Flats Field Office

10808 Highway 93, Unit A

Golden, CO 80403-8200

RE: Closeout Reports for Buildings 553, 554, 427, 449, 449C, and T131A

Dear Mr. Legare:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the Closeout Reports for Buildings 553, 554, 427, 449, 449C, and T131A, dated August 14, 2003. Since these Buildings were previously determined to be Type 1 Facilities we appreciate being provided these Closeout Reports for our information. We have the following comments:

T131A - It is indicated that this trailer was removed and no additional infrastructure remains. However, at a minimum there are concrete pads that were associated with this trailer that need to be removed and should have been identified in the Closeout Report. A map showing the location of this trailer and any remaining infrastructure should have been provided.

B553 and B554 - Since B553 was also the former chemical dispensary with a drain to a gravel lined pit, the disposition of this drain should have been discussed. Maps showing the location of these buildings and location and condition of remaining in-ground utilities should have been provided with these Closeout Reports.

As we have previously discussed, these Closeout Reports should include a map of the facility identifying the structures involved, those removed, and all remaining infrastructure and its condition. This information and map are necessary for possible ER and/or future stewardship concerns. As such, maps need to be provided for Buildings 553, 554, and T131A.

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruckek at (303) 692-3328.

Sincerely,


Steven H. Gunderson
RFCA Project Coordinator

cc: Steve Tower, DOE
Tim Rehder, EPA
Karen Wiemelt, KH
David Abelson, RFCLOG

Cameron Freiboth, KH
Dave Shelton, KH
Steve Nesta, KH
Administrative Records Building T130G


Reviewed for Addressee
Corres. Control RFP10/15/03
Date

By

Ref. Ltr. #

DOE ORDER #

5400.1

ADMIN RECORD

IA-A-001713